



Phone: 1-800-757-3747 or 1-630-543-3747 | Fax: 1-630-543-0498 | Email: support@dicksondata.com | Website: DicksonData.com

8" (203mm) Temperature & Humidity Chart Recorder



Specifications

Ambient Operating RH Conditions: 0-95% RH non-condensing Ambient Operating Temperature Conditions: 32.0 to 120.0F (0.0 to 50.0C) Approvals: CE Battery Life (Avg): At 32°F: 24-Hour Chart Rotation = 3 Weeks; 7-Day Chart Rotation = 4 Months; At 70°F: 24-Hour Chart Rotation = 1 Month; 7-Day Chart Rotation = 6 Months Calibration Options: N100, N300, N400 Channels: CH1: Temperature, CH2: Humidity Chart Rotation Speed: 24 Hour or 7 Day Dew Point Accuracy: +/-5.0F from 30.0 to 95.0% RH (Calculated) (+/-3.0C from 30.0 to 95.0% RH (Calculated)) Dew Point Range: 32.0 to 122.0F (0.0 to 50.0C) **Dimensions:** 3.1 x 9.2 x 9.2in **Display Resolution:** 0.1 **Enclosure:** Rugged Black ABS Case, Polycarbonate Door, Aluminum Dial Humidity Accuracy: +/-3.0% RH from 5.0 to 95.0% Humidity Range: 0-95% RH non-condensing Humidity Sensor Type: Field Replaceable IP Rating: 20 Included Accessories: Four AA Batteries, Red and Blue Pen and Quick Start Guide. *Charts sold separately. Keypad Functions: Power On/Off, Pen Home Mounting Options: Free Standing or Wall Mount (With Keyhole) Power Source: Battery; Four AA Batteries (User Replaceable) Power Status Indicator: LED Indicator **Remote Sensor Length:** Single 10 ft extension cable available (without sacrificing accuracy) **Response Time:** 5 Minutes to 63% of Full Scale

Temperature Accuracy: +/-1.0F from 32.0 to 120.0F (+/-0.6C from 0.0 to 50.0C) Temperature Range: 32.0 to 120.0F (0.0 to 50.0C) Unit Weight: 4.6 lbs Units/Pkg: 1 Warranty: 12-Month Limited





Phone: 1-800-757-3747 or 1-630-543-3747 | Fax: 1-630-543-0498 | Email: support@dicksondata.com | Website: DicksonData.com

Calibrations

N100: 1-Point NIST Traceable Calibration

- **N300:** 3-Point NIST Traceable Calibration
- N400: 3-Point Ultima NIST A2LA Accredited Calibration

Accessories



R200 - Replaceable Temperature/Humidity Sensor Angled Temperature/Humidity Replaceable Sensor



R180 - Replacement AC Adapter AC Adapter for TSB/TWE/TWP Loggers and the KT8/KT6 series.







A062 - AC Adapter Extension Cable 10' 10' Power Extension for R157 AC Adapter





Phone: 1-800-757-3747 or 1-630-543-3747 | Fax: 1-630-543-0498 | Email: support@dicksondata.com | Website: DicksonData.com

Accessories



A868 - Sensor Dust Filter Sensor Dust Filter - prolong the life of your sensor.