

Phone: 1-800-757-3747 or 1-630-543-3747 | Fax: 1-630-543-0498 | Email: support@dicksondata.com | Website: DicksonData.com

6" (152mm) Temperature & Humidity Chart Recorder



Specifications

Ambient Operating RH Conditions: 0-95% RH non-condensing

Ambient Operating Temperature Conditions: 32.0 to 122.0F (0.0 to 50.0C)

Approvals: RoHS, CE

Battery Backup: 9V Battery Back-up. Powers unit for up to 3 days.

Battery Life (Avg): 72 Hours (Back-up Only) **Calibration Options:** N100, N300, N400 **Channels:** CH1: Temperature, CH2: Humidity **Chart Rotation Speed:** 24 Hour or 7 Day

Dimensions: 3.25 x 7.56 x 7.56in **Display Dimensions Height:** 1.18 **Display Dimensions Width:** 0.59

Display Resolution: 0.1 Degree from -9.9 to 199.9; 1 Degree resolution above 2000 and below 9.9

Display Type: LCD

Enclosure: Rugged Black ABS Case, Polycarbonate Door, Aluminum Dial

Humidity Accuracy: +/-2.0% RH from 0.0 to 60.0%; +/-3.0% RH from 60.0 to 95.0%

Humidity Range: 0-95% RH non-condensing

IP Rating: 21

Included Accessories: AC Adapter, Red and Blue Pen, 9V Battery, Quick Start Guide. *Charts sold separately.

Keypad Functions: Power On/Off, Pen Home

Mounting Options: Free Standing or Wall Mount (With Keyhole)

Power Cord: 6 ft

Power Source: 120 to 240 VAC, 12 VDC (INTL fittings available); AC Adapter

Power Status Indicator: LED Indicator

Response Time: 5 Minutes to 63% of Full Scale

Temperature Accuracy: +/-1.8F from 32.0 to 100.0F (+/-1.0C from 0.0 to 50.0C)

Temperature Range: 32.0 to 100.0F (0.0 to 50.0C)

Unit Weight: 9 lbs

Units/Pkg: 1

Warranty: 12-Month Limited



Phone: 1-800-757-3747 or 1-630-543-3747 | Fax: 1-630-543-0498 | Email: support@dicksondata.com | Website: DicksonData.com

Calibrations

N100: 1-Point NIST Traceable Calibration **N300:** 3-Point NIST Traceable Calibration

N400: 3-Point Ultima NIST A2LA Accredited Calibration

Accessories



R180 - Replacement AC Adapter AC Adapter for TSB/TWE/TWP Loggers and the KT8/KT6 series.



R066 - Universal Plug Kit for Data Loggers International Plug Kit for Data Loggers



A062 - AC Adapter Extension Cable 10' 10' Power Extension for R157 AC Adapter



A868 - Sensor Dust Filter Sensor Dust Filter - prolong the life of your sensor.



Phone: 1-800-757-3747 or 1-630-543-3747 | Fax: 1-630-543-0498 | Email: support@dicksondata.com | Website: DicksonData.com

Accessories



A896 - Probe Extension Cable 10' Extension Probe for Straight Pre-Calibrated Sensor



R007 - 9V Battery 9V Battery